


Figure T-8: Walking Audit Issues & Opportunities - State Park Drive and Soquel Drive



All maps are available at a larger size online at [www.transitcorridorsplan.org](http://www.transitcorridorsplan.org)  
 Source: Fehr & Peers, 2012

- Missing Sidewalk
- Walking Audit Area
- - - - - Railroad
- = Crosswalk

